



IDAHO DEPARTMENT OF
HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T. – Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0036
PHONE: (208) 334-6626
FAX: (208) 364-1888
E-mail: fsb@dhw.idaho.gov

September 8, 2008

Russell McCoy, Administrator
Rulon House Group Home
415 South Arthur
Pocatello, Idaho 83204

RE: Rulon House Group Home, provider #13G020

Dear Mr. McCoy:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Rulon House Group Home, on August 26, 2008.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208)334-6626.

Sincerely,

ERIC MUNDELL, REHS
Health Facility Surveyor
Facility Fire Safety and Construction Program

EM/lj

Enclosure

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/08/2008
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 13G020	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - ENTIRE STRUCTURE B. WING _____		(X3) DATE SURVEY COMPLETED 08/26/2008
NAME OF PROVIDER OR SUPPLIER RULON HOUSE GROUP HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 2369 RULON POCATELLO, ID 83201		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
K 000	<p>INITIAL COMMENTS</p> <p>Surveyor: 08378 The facility is a two story, type V(000) residential type building with sleeping rooms on both levels. There are ground level exits on each level. It is sprinklered in living areas and closets. There is a complete fire alarm system with full smoke detection coverage. Currently it is licensed for 8 ICF/MR beds.</p> <p>The above facility was found to be in substantial compliance during the annual Fire/Life Safety survey conducted on August 26, 2008. The facility was surveyed under the LIFE SAFETY CODE, 2000 Edition, Chapter 33, Existing Residential Board & Care Occupancies, Impractical Evacuation Capability in accordance with 42 CFR 483.470 (j).</p> <p>The Survey was conducted by:</p> <p>Eric Mundell REHS Health Facility Surveyor Fire/Life Safety and Construction</p>	K 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 13G020	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED 08/26/2008
NAME OF PROVIDER OR SUPPLIER RULON HOUSE GROUP HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 2369 RULON POCATELLO, ID 83201		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
M 000	<p>16.03.11 Initial Comments</p> <p>The facility is a two story, type V(000) residential type building with sleeping rooms on both levels. There are ground level exits on each level. It is sprinklered in living areas and closets. There is a complete fire alarm system with full smoke detection coverage. Currently it is licensed for 8 ICF/MR beds. A temporary variance had been addressed.</p> <p>The above facility was found to be in substantial compliance during the annual Fire/Life Safety survey conducted on August 26, 2008. The facility was surveyed under the LIFE SAFETY CODE, 2000 Edition, Chapter 33, Existing Residential Board & Care Occupancies, Impractical Evacuation Capability and in accordance with IDAPA 16.03.11 Rules Governing Intermediate Care Facilities for the Mentally Retarded (ICF/MR).</p> <p>The Survey was conducted by:</p> <p>Eric Mundell REHS Health Facility Surveyor Fire/Life Safety and Construction</p>	M 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE